

# Environmental Impact Assessment Report

Teindland Wind Farm

**Volume 2a**

**EIA Report Figures**

April 2025



# TABLE OF CONTENTS

## Environmental Impact Assessment Report – Figures

Figure 1.1	Site Location
Figure 1.2	Site Boundary
Figure 3.1	Environmental Designations
Figure 3.2	Onsite Constraints
Figure 3.3a	Scoping Layout
Figure 3.3b	Pre-Chilled Layout
Figure 3.3c	Design Chill
Figure 3.3d	Design Freeze
Figure 4.1	Site Location
Figure 4.2a	Indicative Turbine Elevations 200m Tip Height
Figure 4.2b	Indicative Turbine Elevations 230m Tip Height
Figure 4.3	Typical Turbine Foundations
Figure 4.4	Typical Crane Hardstanding
Figure 4.5	Typical Cable Trench
Figure 4.6	Typical Substation Layout and Elevations
Figure 4.7	Typical BESS Layout
Figure 4.8	Typical Control Building & BESS Elevations
Figure 4.9	Typical Construction Compound
Figure 4.10	Typical Track Details
Figure 4.11	Typical Watercourse Crossings
Figure 4.12	Proposed Site Entrance
Figure 4.13	Typical Meteorological Mast
Figure 5.1	ZTV Bareground
Figure 5.2	ZTV
Figure 5.3	Topography and Landcover
Figure 5.4	Landscape Character
Figure 5.5	Landscape Character and ZTV
Figure 5.6	Visual Receptors
Figure 5.7	Night Time
Figure 5.8	Aviation Lighting ZTV
Figure 5.9	Cumulative Sites
Figure 5.10	Cumulative ZTV – Operational and Consented
Figure 5.11	Cumulative ZTV – Planning
Figure 6.1	Habitat Survey Results
Figure 6.2	LEPO Woodland within Extended Survey Boundary
Figure 6.3	Static Detector Locations
Figure 6.4	Fish Habitat Survey Locations
Figure 6.5	Designated Sites
Figure 7.1	Vantage point locations and viewsheds;

Figure 7.2	Baseline ornithology survey areas
Figure 7.3	Site regional context (Natural Heritage Zones);
Figure 7.4	Statutory designated sites with ornithological interests
Figure 7.5a	Flight activity survey results Year 1 - pink-footed goose
Figure 7.5b	Flight activity survey results Year 1 - target species excluding osprey and pink-footed goose
Figure 7.5c	Flight activity survey results Year 2 - pink-footed goose
Figure 7.5d	Flight activity survey results Year 2 - target species excluding osprey and pink-footed goose
Figure 8.1	Cultural Heritage – Inner Study Area
Figure 8.2	Cultural Heritage – Abnormal Load Delivery Route
Figure 8.3	Cultural Heritage – Outer Study Area with ZTV without Screening
Figure 8.4	Cultural Heritage – Outer Study Area with ZTV with Screening
Figure 9.1	Noise Contour Plot
Figure 11.1	Study Area
Figure 11.2	Traffic Counter Locations
Figure 11.3	Abnormal Loads Route
Figure 12.1	Study Areas
Figure 12.2	Core Study Area Catchments
Figure 12.3	Badentinan Groundwater Risk Zone
Figure 12.4	Private Water Supply Sources
Figure 14.1	Core Paths and Recreational Routes
Figure 15.1	Shadow Flicker Assessment